

## Tolzin, Carrington <carrington.tolzin@dnr.iowa.gov>

## Cahter Oak

1 message

Lynam, Anne <anne.lynam@dnr.iowa.gov>

Fri, Dec 29, 2017 at 10:05 AM

To: Carrington Tolzin <carrington.tolzin@dnr.iowa.gov> Cc: "Warren, James" <james.warren@dnr.iowa.gov>

Here is info from the file on lead and copper siting plan. No known lead service lines.

From the file city had galvanized water main. Several main replacement projects to replace it with PVC.

PWS has regularly taken more lead and copper samples than required. When needed 10 took 15. When needed 5 took 8. No results over ALE. Had pH adjustment as corrosion control listed in some older permits.

Anne



Anne Lynam | Environmental Specialist Sr Iowa Department of Natural Resources P 515-725-0280 | F 515-725-8202 | 502 E. 9th St., Des Moines, IA 50319 www.iowadnr.gov



served by lead service lines

## Part B.

## Explanation

- No. 2 Going by building Permits. The City of Charter Oak had only 5 houses built after 1982 that had copper pipe with lead solder.
- No. 3 Going by reports from former water superintendent and from local plumber and service reports. The City doesn't havelead service lines that are known.